

Product details: NW1650H Machine plasma torch 7.5m  
(POWERMAX 1650 connection)

product code: NW03831CX-HY  
product ean: 5900391245323



Standard **HYPERTHERM® POWERMAX 1650®**

## Product variants

| Index   | Price                            |
|---|----------------------------------|
| <b>NW1650H Machine plasma torch 7.5m (POWERMAX 1650 connection)</b><br>NW03831CX-HY         | <b>€670.28 / pc</b><br>Net price |
| <b>NW1250H Hand plasma torch 7.5m (POWERMAX 1000/1250 connection)</b><br>NW03820CX-HY       | <b>€522.97 / pc</b><br>Net price |
| <b>NW1250H Hand plasma plasma torch 15m (POWERMAX 1000/1250 connection)</b><br>NW03825CX-HY | <b>€696.96 / pc</b><br>Net price |
| <b>NW1250H Machine plasma torch 7.5m (POWERMAX 1000/1250 connection)</b><br>NW03830CX-HY    | <b>€662.75 / pc</b><br>Net price |
| <b>NW1250H Machine plasma torch 15m (POWERMAX 1000/1250 connection)</b><br>NW03835CX-HY     | <b>€836.89 / pc</b><br>Net price |
| <b>NW1650H Hand plasma torch 7.5m (POWERMAX 1650 connection)</b><br>NW03821CX-HY            | <b>€528.50 / pc</b><br>Net price |
| <b>NW1650H Hand plasma torch 15m (POWERMAX 1650 connection)</b><br>NW03826CX-HY             | <b>€704.55 / pc</b><br>Net price |
| <b>NW1650H Machine plasma torch 15m (POWERMAX 1650 connection)</b><br>NW03836CX-HY          | <b>€844.32 / pc</b><br>Net price |

## Technical details

|                           |                        |
|---------------------------|------------------------|
| Type of torch             | machine                |
| Standard                  | HYPERTHERM®            |
| Length                    | 7.5m                   |
| Cutting current           | 40-130A                |
| Gas                       | air / N2               |
| Duty cycle                | 60% (130A), 85% (100A) |
| Recommended work pressure | 4.6 - 5.5bar           |
| Air flow                  | 290l/min               |

---

|                         |                       |
|-------------------------|-----------------------|
| <b>Arc ignition</b>     | <b>without HF</b>     |
| <b>Connection</b>       | <b>PowerMax1650®</b>  |
| <b>Pilot arc</b>        | <b>18 - 22A</b>       |
| <b>Type HYPERTHERM®</b> | <b>POWERMAX 1650®</b> |

---